

HERE'S A CHALLENGE ...

Challenge Pulleys,

Loads More, Costs Less.



Lock in to:

Secure source of supply • Superior service
Product quality and reliability • Manufacturers prices
Securing more than just your profits

Never a problem always a ...

CHALLENGE[®]

www.challengept.com

technicalsupport@challengeproduction.com



Challenge V - Pulley Range

| SPZ/Z | | | | | | | | |
|-------|---------|---|---|---|---|---|---|--|
| PCD | Grooves | | | | | | | |
| | 1 | 2 | 3 | 4 | 5 | 6 | 8 | |
| 56 | • | • | | | | | | |
| 60 | • | • | | | | | | |
| 63 | • | • | • | | | | | |
| 67 | • | • | • | | | | | |
| 71 | • | • | • | • | | | | |
| 75 | • | • | • | • | | | | |
| 80 | • | • | • | • | | | | |
| 85 | • | • | • | • | • | | | |
| 90 | • | • | • | • | • | • | | |
| 95 | • | • | • | • | • | • | | |
| 100 | • | • | • | • | • | • | | |
| 106 | • | • | • | • | • | • | | |
| 112 | • | • | • | • | • | • | | |
| 118 | • | • | • | • | • | • | | |
| 125 | • | • | • | • | • | • | | |
| 132 | • | • | • | • | • | • | | |
| 140 | • | • | • | • | • | • | | |
| 150 | • | • | • | • | • | • | | |
| 160 | • | • | • | • | • | • | | |
| 170 | • | • | • | • | • | • | | |
| 180 | • | • | • | • | • | • | | |
| 190 | • | • | • | • | • | • | • | |
| 200 | • | • | • | • | • | • | • | |
| 224 | • | • | • | • | • | • | • | |
| 250 | • | • | • | • | • | • | • | |
| 280 | • | • | • | • | • | • | • | |
| 315 | • | • | • | • | • | • | • | |
| 355 | • | • | • | • | • | • | • | |
| 400 | • | • | • | • | • | • | • | |
| 450 | • | • | • | • | • | • | • | |
| 500 | • | • | • | • | • | • | • | |
| 560 | | • | | | | | | |
| 630 | | • | • | • | • | | | |

| SPA/A | | | | | | |
|-------|---------|---|---|---|---|---|
| PCD | Grooves | | | | | |
| | 1 | 2 | 3 | 4 | 5 | 6 |
| 63 | • | • | | | | |
| 67 | • | • | | | | |
| 71 | • | • | • | | | |
| 75 | • | • | • | | | |
| 80 | • | • | • | | | |
| 85 | • | • | • | | | |
| 90 | • | • | • | • | | |
| 95 | • | • | • | • | • | |
| 100 | • | • | • | • | • | • |
| 106 | • | • | • | • | • | • |
| 112 | • | • | • | • | • | • |
| 118 | • | • | • | • | • | • |
| 125 | • | • | • | • | • | • |
| 132 | • | • | • | • | • | • |
| 140 | • | • | • | • | • | • |
| 150 | • | • | • | • | • | • |
| 160 | • | • | • | • | • | • |
| 170 | • | • | • | • | • | • |
| 180 | • | • | • | • | • | • |
| 190 | • | • | • | • | • | • |
| 200 | • | • | • | • | • | • |
| 212 | • | • | • | • | • | • |
| 224 | • | • | • | • | • | • |
| 236 | • | • | • | • | • | • |
| 250 | • | • | • | • | • | • |
| 280 | • | • | • | • | • | • |
| 300 | • | • | • | • | • | • |
| 315 | • | • | • | • | • | • |
| 355 | • | • | • | • | • | • |
| 400 | • | • | • | • | • | • |
| 450 | • | • | • | • | • | • |
| 500 | • | • | • | • | • | • |
| 560 | | • | • | • | • | • |
| 630 | | • | • | • | • | • |
| 800 | | • | • | • | • | • |

| SPB/B | | | | | | | | | |
|-------|---------|---|---|---|---|---|---|----|--|
| PCD | Grooves | | | | | | | | |
| | 1 | 2 | 3 | 4 | 5 | 6 | 8 | 10 | |
| 100 | • | • | • | | | | | | |
| 106 | • | • | • | | | | | | |
| 112 | • | • | • | | | | | | |
| 118 | • | • | • | | | | | | |
| 125 | • | • | • | • | | | | | |
| 132 | • | • | • | • | • | | | | |
| 140 | • | • | • | • | • | • | | | |
| 150 | • | • | • | • | • | • | | | |
| 160 | • | • | • | • | • | • | | | |
| 170 | • | • | • | • | • | • | | | |
| 180 | • | • | • | • | • | • | | | |
| 190 | • | • | • | • | • | • | • | | |
| 200 | • | • | • | • | • | • | • | | |
| 212 | • | • | • | • | • | • | • | | |
| 224 | • | • | • | • | • | • | • | • | |
| 236 | • | • | • | • | • | • | • | • | |
| 250 | • | • | • | • | • | • | • | • | |
| 280 | • | • | • | • | • | • | • | • | |
| 300 | • | • | • | • | • | • | • | • | |
| 315 | • | • | • | • | • | • | • | • | |
| 335 | • | • | • | • | • | • | • | • | |
| 355 | • | • | • | • | • | • | • | • | |
| 375 | | | | | | | | | |
| 400 | • | • | • | • | • | • | • | • | |
| 450 | • | • | • | • | • | • | • | • | |
| 500 | • | • | • | • | • | • | • | • | |
| 560 | • | • | • | • | • | • | • | • | |
| 630 | • | • | • | • | • | • | • | • | |
| 710 | | • | • | • | • | • | • | • | |
| 800 | | • | • | • | • | • | • | • | |
| 900 | | • | • | • | • | • | • | • | |
| 1000 | | • | • | • | • | • | • | • | |
| 1250 | | • | • | • | • | • | • | • | |

| SPC/C | | | | | | |
|-------|---------|---|---|---|---|----|
| PCD | Grooves | | | | | |
| | 3 | 4 | 5 | 6 | 8 | 10 |
| 200 | • | • | • | • | • | • |
| 212 | • | • | • | • | • | • |
| 224 | • | • | • | • | • | • |
| 236 | • | • | • | • | • | • |
| 250 | • | • | • | • | • | • |
| 265 | • | • | • | • | • | • |
| 280 | • | • | • | • | • | • |
| 300 | • | • | • | • | • | • |
| 315 | • | • | • | • | • | • |
| 335 | • | • | • | • | • | • |
| 355 | • | • | • | • | • | • |
| 375 | • | • | • | • | • | • |
| 400 | • | • | • | • | • | • |
| 425 | • | • | • | • | • | • |
| 450 | • | • | • | • | • | • |
| 475 | • | • | • | • | • | • |
| 500 | • | • | • | • | • | • |
| 530 | • | • | • | • | • | • |
| 560 | • | • | • | • | • | • |
| 630 | • | • | • | • | • | • |
| 710 | • | • | • | • | • | • |
| 800 | • | • | • | • | • | • |
| 1000 | • | • | • | • | • | • |
| 1250 | • | • | • | • | • | • |

The benefits

'V' AND WEDGE BELT PULLEYS

- Broad range of sizes
- Manufactured from high grade iron
- Balanced to Q6.3
- Range of variable speed pulleys



Never a problem always a ...

CHALLENGE®

www.challengept.com

